

Buildings and Architectural Styles Boñar, León 2013

Ficha Técnica
Inteviewer: David Macko
Informant: Juan Carlos Martínez Saraz
June 2013
Boñar, León, Spain
Language: English ¹

Definition of Rammed earth: the use of sustainable products like dirt, clay, stone, chalk, lime, and gravel to create a structure.

¹ Dirección de contacto. Proyecto La Alcordanza: Juan José Gutiérrez Álvarez, Division of Social and Behavioral Sciences. 100 Campus Center, Seaside, CA 93955. California State University, Monterey Bay. Teléfono +1(831)582-4621.

Table

R_ID	Image Name	Description	Comments
1.	Macko_001 Macko_003 Macko_004 Macko_005	Building address 10. Bottom floor two stastreet looking south. Vorvic and Tabacos stores facing West along Avenida de La Caixa, Salón Belleza, Sara Bello, and BaDiana.	s shop. Three Builiding materials brick, Consitución. glass, iron. Used to be a
2	Macko_002	Building address 56. Rammed earth wall wood framing. Stone only exposed on bo around windows.	
3	Macko_006	Building address 33. Rammed earth.	Built in the late 1800s. Apartments on top of Cereza Pasteleria and Diaro de Leon. Stone base. Decorative iron balconies.

La Alcordanza

R_ID	Image Name	Description	Comments
4	Macko_007	Building address 45. Stone base. Unsure of building style. Rammed earth or brick.	Built in early 1900s. Most likely brick with stone. Stucko.
5	Macko_008	Building address 47. Brick work around windows. 3 stories.	Built in early 1940s.
6	Macko_009	Building address 53. Two story house. Extends back onto property with area around building.	Built in 1896. Normally contains sheep and a dog. For sale
7	Macko_010	Building address 61. Two story house. Stone walls top to bottom. Top balcony inscription with date of construction.	Built in 1877. Restored in 2011.

R_ID	Image Name	Description	Comments
8	Macko_011	Building address 67. Two story house. Green tile on second floor.	Used to be a gaseos facotry. When Almato Alonso died the house was given to two people and they split the house in two.
9	Macko_011	Building address 69. Two story house. Does not have tile on second floor.	The second half of the house.
10	Macko_012	Building Address 73. Two story house. Green windows. Brick building. Bricks covered with stucko or talcome combine.	Built in 1920-1915. Exposed brick at bottom. Coloums made to look like stone.

La Alcordanza

R_ID	Image Name	Description	Comments
11	Macko_013	Building address 92. Two story house. Red paint on outside.	Built in 1850s. Windows inbetween modern large glass windows and old style small windows.
12	Macko_014	Building address 17. Multi story house. Front gate La Calzada.	Built in 1980s.
13	Macko_015	Building address 4. Apartment building and Dia supermarket.	Dia opened up 2 summers ago. The apartment buildings built in 1970s.

R_ID	Image Name	Description	Comments
14	Macko_016	Buldings 74 and 76. Two story buildings.	Built in later 1700s.
15	Macko_017	Building address 43. Two story windows tall. Door tall. Stone work. Rammed earth.	
16	Macko_018	Building 29. Two story. Small door Rammed earth method.	Stone on bottom and proceeds to top. Windows allow some light in.
17	Macko_019	Building 27. Two story small windows.	Built in 1550s. Small roof keeps heat in the living space would be just a little taller than entry for walking around.

La Alcordanza

R_ID	Image Name	Description	Comments
18	Macko_020	Building 47. Two story. Rammed earth. Arched door way. Engraving over arched door "Abe Maria" Stone patern on bottom.	Good stone supporting arch. Exposed rock on the bottom.
19	Macko_021	Building 86. Two story. Brick built. Covered brick.	Brick covered but at the bottom can see it cracking. Used to be a lard and milk factory. But it is now empty.
20	Macko_022	Building 17. Two story. Stone work. Door covered with symbols of Pharmacueticals(snakes around a pole) and merchant.(horn of abundance) crowed by the symbol of Mars	Built in 1896. Rounded stone at the gate bases to prevent the carraige wheels from hitting fence posts.
21	Macko_023		